

# Haier

# SERVICE BULLETIN



Issue Date(y-m-d)	2012-12-20
SB No.	ASSBDAC13071601A
Factory Division	Air Conditioner
Editor	Xue Xiaohui
Tel	86 532 88935350
E-mail	Xuexiaohui.ac@haier.com

## APPLICABILITY

Product	Air Conditioner	Change Reason Code	1
Effective Date(y-m-d)	2013-08-15	Compatibility Code	C
Involved Models	Effective S/N (From)	Effective S/N (To)	
#1		/	





## SUBJECT

Item	Before Change	After Change
Part No.	A0011800334 + A0011800238	A0011800334 + A0011800238
Description	PCB plug	PCB plug
Change Reason & Improvements	To improve performance	

Pictures Before Change	Pictures After Change
 <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="border: 1px solid black; padding: 2px;">A0011800334</div> <div style="border: 1px solid black; padding: 2px;">A0011800238</div> </div> <p style="text-align: center; border: 1px solid black; padding: 5px;">Before: the plugs are on the PCB</p>	 <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="border: 1px solid black; padding: 2px;">A0011800334</div> <div style="border: 1px solid black; padding: 2px;">A0011800238</div> </div> <p style="text-align: center; border: 1px solid black; padding: 5px;">Now: the plug is in the middle of the wire</p>

Note	1. This changed the wire connection type.
	2. For old part, should apply for A0011800334 + A0011800238, because the new part is not commonly used with old part. For new part can apply the fault one singly.

## REFERENCE

Compatibility Code				Change Reason Code	
	Parts	Set	Explanation	1	To improve productivity
A	Original		Original or new parts may be used in early or late production sets. Use original parts until exhausted. then stock new parts	2	New part supplier
	New			Late	3
B	Original		Original parts may be used in early production sets only. New parts may be used in early or late production sets. Use original parts where possible. Then stock new parts.	4	Parts added
	New			Late	5
C	Original		New parts only may be used in early or late production sets. Stock new parts	6	Performance improvement
	New			Late	7
D	Original		Original parts only may be used in early production sets. New parts may be used in late production sets only. Stock original and new parts	8	Comply whit ROHS
	New			Late	

<b>Service Bulletin No.</b> (e.g.: ASSBCDW06072401B): <b>1AS:</b> prefix after sales <b>2.SB:</b> service bulletin. <b>3.C:</b> release no.. <b>4.DW:</b> product code dish washer. <b>5. 60724:</b> issue date: 2006-July-24 <sup>th</sup> . <b>6.01:</b> intraday S/N. <b>7.B:</b> with service bulletin procedure; <b>A:</b> without service bulletin procedure.	<b>Product Code:</b> <b>(RF:</b> refrigerator; <b>FZ:</b> freezer; <b>AC:</b> air conditioner; <b>CC:</b> commercial air conditioner; <b>TV:</b> television; <b>TL:</b> top load washing machine; <b>FL:</b> front load washing machine; <b>MW:</b> microwave oven; <b>DW:</b> dish washer);	<b>Notice</b> 1. Please file this sheet with relative technical documents 2. Questions, please E-mail to editor and cc to <haiereurope@haier.com> 3. Appeals, please E-mail to <haiereurope@haier.com>
---	---	---

NO.	Involved Models	Effective S/N (From)	Effective S/N (To)	Effective Date(y-m-d)	Country
1	DE45EK-L	AJ0253E00		2012-12-20	America
2	DE45EK-T	AJ0256E00		2012-12-20	America
3	ADHH50LPW1	AJ0259E00		2012-12-20	America
4	DE45EM	AJ025FE00		2012-12-20	America
5	DE65EK-L	AJ0261E00		2012-12-20	America
6	DE65EM	AJ0291E00		2012-12-20	America