55PFL5601/F7 (Serial No.: DS1) A51RJUH SERVICE ADDITIONAL SHEET Notification on wiring

Corresponding Models

55PFL5601/F7 (DS1)

• Symptom

When replacing the Digital Main CBA Unit, replace it along with the Wire Assembly. When removing the Digital Main CBA Unit from the Main Unit, remove it along with the Wire Assembly and use them in pairs.

55PFL5601/F7 model has the combination of more than one Wire Assembly and Digital Main CBA Unit. See the following table for more information.


Digital Main CBA Unit Connecter Direction

A51RJMMA-001



Wire Assembly Parts No.

WX1A51RET313



WX1A51RJT303

